Scope of	Work for Property Lo	cated	at: 1	916-	8 West Galena Street		
	Property is: Single Fa	mily [] [uplex	☑ Other□		
Date:	12/8/2015						
take no respo	nsibility for problems discovered	after the ir	spect	tion dat	The City of Milwaukee, the Redevelopmer, or for omissions through error or oversighteral Block Grant or HOME programs.		
Exterior	Condition Report						
Location Site	Required Work Landscaping	n/a <u>[</u>	<u>Y</u>	es 🗆	Note/Comments Self Help	\$	Cost
	Steps/Handrails	n/a [Z Y	es 🗆		\$	
	Service walks	n/a [✓ Y	es 🗆		\$	
	Fencing	n/a _	7 Y	es 🗆		\$	
	Parking	n/a _	7 Y	es 🗆		\$	
	Retaining walls	n/a_	Z Y	es 🗆		\$	
	Other	n/a [_ Y	es 🗆		\$	
	Other	n/a [] Y	es 🗆		\$	
Garage	Singles: repair	n/a 🗓	y Y	es 🗆		\$	
	Shingles: Roof over existing	n/a 🕓	7 Y	es 🗆		\$	
	Shingles:Tear off & re-roof	n/a 🖸	2 Y	es 🗆		\$	
	Gutters/downspouts	n/a 🕓	Z Y	es 🗆		\$	
	Flashing	n/a 🖸	7 Y	es 🗆		\$	
	Eaves	n/a [7 Y	es 🗆		\$	
	Siding	n/a [_ Y	es 🗸	minor repairs	\$	500.00
	Doors	n/a [] Y	es 🗸		\$	1,000.00
	Windows	n/a [7 Y	es 🗆		\$	
	Slab	n/a 🕓	7 Y	es 🗆		\$	
	Paint	n/a [7 Y	es 🗆		\$	
	Electrical	n/a [7 Y	es 🗆		\$	
	Other	n/a [] Y	es 🗸	address numbers	\$	10.00
Porches	Roof	n/a [7 Y	es 🗆		\$	
	Deck-upper	n/a _	<u> Y</u>	es 🗆		\$	
	Decklower	n/a _	/ Y	es 🗆		\$	
	Steps/handrails	n/a _	<u> Y</u>	es 🗆		\$	
	Ceiling	n/a [<u> Y</u>	es 🗆	_	\$	
	Guardrails	n/a [Y	es 🔽	replace pickets	\$	400.00
	Structural	n/a 5	 Л У	es 🗆		\$	

n/a ☐ Yes ☑ both

n/a 🗌 Yes 🗌

\$

\$

400.00

Paint

Other

House

Chimney	n/a ☑	Yes □		\$
Shingles: repair	n/a □	Yes ☑		\$ 500.00
Shingles: Roof over existing	n/a ☑	Yes □		\$
Shingles:Tear off & re-roof	n/a ☑	Yes □	_	\$
Gutters/downspouts	n/a □	Yes ☑	repairs only	\$ 250.00
Flashing	n/a ☑	Yes □		\$
Eaves	n/a ☑	Yes □	_	\$
Siding	n/a □	Yes ✓	missing pieces	\$ 2,000.00
Storm Doors	n/a ☑	Yes 🗆		\$
Prime ("main") Doors	n/a □	Yes ✓		\$ 1,500.00
Storm Windows	n/a ☑	Yes 🗆		\$
Prime ("main") Windows	n/a □	Yes ☑		\$ 2,000.00
Paint	n/a ☑	Yes 🗆		\$
Foundation	n/a □	Yes ☑	masonry repair	\$ 500.00
Electrical	n/a ☑	Yes 🗆		\$
Other	n/a □	Yes 🗆		\$
Other	n/a □	Yes 🗆		\$
Other	n/a □	Yes 🗆		\$
Other	n/a □	Yes □		\$

Exterior: Estimated Cost:* \$ 9,060.00

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report Unit: Entire unit (single family)			Lower unit of duplex	v	
Mechanical Heating	Upper unit of duplex Required Work			Other		
-	Repair/replace boiler	n/a ☑	Yes 🗆			\$
	Repair radiation	n/a ☑	Yes 🗆			\$
	Repair/replace furnace	n/a □	Yes ☑			\$ 3,300.00
	Repair ductwork	n/a □	Yes ☑			\$ 500.00
	Replace thermostat	n/a ☑	Yes 🗆			\$
	Repair/replace grilles	n/a ☑	Yes □			\$
Electrical	Tune boiler/furn. insp ht exchang	€n/a ☑	Yes 🗆	_		\$
Liectrical	Repair/replace receptacles	n/a □	Yes ☑			\$ 450.00
	Repair/replace switches	n/a □	Yes ☑			\$ 450.00
	Repair/replace fixtures	n/a □	Yes ☑			\$ 500.00
	Install outlets and circuits	n/a □	Yes ☑			\$ 1,000.00
	Install outlets and circuits	n/a ☑	Yes □			\$
	Install outlets and circuits	n/a ☑	Yes 🗆			\$
	Install outlets and circuits	n/a ☑	Yes 🗆			\$
	Upgrade service	n/a □	Yes ☑			\$ 900.00
	Other	n/a □	Yes 🗆			\$
-	Other	n/a 🗆	Yes 🗆			\$
Plumbing	Repair/replace kitchen sink	n/a □	Yes □			\$
	Repair/replace kitchen sink fauce	ein/a □	Yes 🗆			\$
	Repair/replace tub	n/a □	Yes 🗆			\$
	Repair/replace tub faucet	n/a □	Yes □			\$
	Repair/replace toilet	n/a □	Yes □			\$
	Repair/replace lavatory	n/a □	Yes 🗆			\$
	Repair/replace lavatory faucet	n/a □	Yes □			\$
	Repair/replace wash tub	n/a □	Yes □			\$
	Repair/replace wash tub faucet	n/a □	Yes □			\$
	Unclog piping:	n/a □	Yes □			\$
	Repair drain/waste/vent piping	n/a □	Yes 🗸			\$ 1,000.00
	Repair water piping	n/a □	Yes 🗸			\$ 1,000.00
	Repair/replace water heater	n/a □	Yes ☑			\$ 750.00
	Other	n/a □	Yes ☑	Complete Bath		\$ 2,500.00
	Other	n/a □	Yes ☑	Complete Kitchen		\$ 1,500.00

Windows	Replace broken glass	n/a ☑	Yes 🛚		\$	
	Repair or replace sash	n/a ☑	Yes 🗆	=	\$	
Doors	Repair or replace doors	n/a □	Yes 🗸		\$	200.00
	Repair or repl. locks/latches	n/a ☑	Yes 🗆	Self Help	\$	
Walls/Ceilin	gs Repair or repl. @ defective	n/a □	Yes ☑		\$	500.00
Paint	Repair or repl. @ defective	n/a □	Yes 🔽		\$	500.00
Fire Safety	Tropair or repi. @ derective	11/α	103 🔯	_	Ψ	300.00
i ile Salety	Install smoke/CO alarm:bsmt.	n/a □	Yes 🗸	Self Help	\$	50.00
	Install smoke/CO alarm: 1st flr.	n/a □	Yes ✓	Self Help	\$	50.00
	Install smoke/CO alarm: 2nd flr.	n/a ☑	Yes □	Self Help	\$	
Handrails	Repair/replace defective	n/a ☑	Yes □	Self Help	\$	
Stairs	Repair defective	n/a 🔽	Yes □		\$	
Floors	Repair defective	n/a □	Yes 🔽		\$	1,800.00
Other		n/a □	Yes □	_	\$,
		n/a □	Yes □		\$	
		n/a □	Yes 🗆	_	\$	
		n/a □	Yes □		\$	

Interior Co	ondition Report							
Mechanical	Unit: Entire unit (single family) Upper unit of duplex Required Work					Lower unit of duplex Other		
Heating	•							
	Repair/replace boiler	n/a	✓	Yes				\$
	Repair radiation	n/a	✓	Yes				\$
	Repair/replace furnace	n/a		Yes	V	_		\$ 3,300.00
	Repair ductwork	n/a		Yes	✓			\$ 500.00
	Replace thermostat	n/a	V	Yes				\$
	Repair/replace grilles	n/a	V	Yes				\$
Electrical	Tune boiler/furn. insp ht exchang	j∈n/a	✓	Yes		_		\$
Licotifical	Repair/replace receptacles	n/a		Yes	V			\$ 450.00
	Repair/replace switches	n/a		Yes	V			\$ 450.00
	Repair/replace fixtures	n/a		Yes	V			\$ 500.00
	Install outlets and circuits	n/a		Yes	V			\$ 1,000.00
	Install outlets and circuits	n/a	V	Yes				\$
	Install outlets and circuits	n/a	V	Yes				\$
	Install outlets and circuits	n/a	V	Yes				\$
	Upgrade service	n/a		Yes	V			\$ 900.00
	Other	n/a		Yes				\$
DI	Other	n/a		Yes				\$
Plumbing	Repair/replace kitchen sink	n/a		Yes		_		\$
	Repair/replace kitchen sink fauce	ein/a		Yes				\$
	Repair/replace tub	n/a		Yes				\$
	Repair/replace tub faucet	n/a		Yes				\$
	Repair/replace toilet	n/a		Yes				\$
	Repair/replace lavatory	n/a		Yes				\$
	Repair/replace lavatory faucet	n/a		Yes				\$
	Repair/replace wash tub	n/a		Yes				\$
	Repair/replace wash tub faucet	n/a		Yes				\$
	Unclog piping:	n/a		Yes				\$
	Repair drain/waste/vent piping	n/a		Yes	V			\$ 1,000.00
	Repair water piping	n/a		Yes	V			\$ 1,000.00
	Repair/replace water heater	n/a		Yes	V	_		\$ 750.00
	Other	n/a		Yes	✓	Complete Bath		\$ 2,500.00

n/a Yes Complete Kitchen

1,500.00

Other

Repair or repl. @ defective	s s selp selp selp selp s	500.00 500.00 500.00
Repair or replace doors	S	500.00 500.00
Walls/Ceilings Repair or repl. @ defective	s s selp selp selp selp s	500.00
Repair or repl. @ defective	selp \$ elp \$ elp \$ elp \$	500.00
Paint Repair or repl. @ defective	selp \$ elp \$ elp \$ elp \$	
Repair or repl. @ defective	elp \$ elp \$ elp \$ elp \$	
Install smoke/CO alarm:bsmt.	lelp \$ lelp \$	50.00
Install smoke/CO alarm: 1st flr.	lelp \$ lelp \$	50.00
Install smoke/CO alarm: 2nd flr.	elp \$	50.00
Handrails Repair/replace defective n/a ☑ Yes ☐ Self Stairs Repair defective n/a ☑ Yes ☐ Floors Repair defective n/a ☐ Yes ☑ Other n/a ☐ Yes ☐	elp \$	50.00
Repair/replace defective n/a ☑ Yes ☐ Self Stairs Repair defective n/a ☑ Yes ☐ Floors Repair defective n/a ☐ Yes ☑ Other n/a ☐ Yes ☐		
Repair defective n/a		
Floors Repair defective n/a Yes Other n/a Yes 1/2	Ψ	
Other n/a Yes	\$	
n/a 🗌 Yes 🔲	\$	1,800.00
n/a ☐ Yes ☐	\$	
	\$	
n/a ☐ Yes ☐	\$	
n/a	\$	
Inte	or: Estimated Cost: \$	33,850.00
Tot	I Exterior and Interior Cost:* \$	42,910.00

Inspected by: Andy Yeager Date: 12/8/15

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 West Mill Road.

 $[\]ensuremath{^*}\text{average}$ contracted cost. Actual costs may vary. Self help will reduce the amount.